

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
1	BRS	L1	9	wet same etch\$3 same "solder bump" same (rotat\$3 or spin\$4)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	2006/02/21 13:48			
2	BRS	L2	317	"solder bump" same (rotat\$3 or spin\$4)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	2006/02/21 13:49			
3	BRS	L3	118	"solder bump" with (rotat\$3 or spin\$4)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	2006/02/21 13:53			
4	BRS	L4	106	2 and @pd<="20010601"	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	2006/02/21 13:54			
5	BRS	L5	40	3 and @pd<="20010601"	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	2006/02/21 13:54			
6	BRS	L6	66	4 not 5	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	2006/02/21 13:54			
7	BRS	L7	22	SRIVASTAVA-KAMALESH-K.in.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	2006/02/21 13:55			
8	BRS	L8	2	CULLINAN-SCHOLL-MARY-C.in.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	2006/02/21 13:56			
9	BRS	L9	15	FANTI-LISA-A.in.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	2006/02/21 14:00			

10	BRS	L10	19	GRIFFITH-JONATHAN-H.in.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	2006/02/21 14:03			
----	-----	-----	----	-------------------------	---	---------------------	--	--	--

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
11	BRS	L11	14	KNARR-RANDOLPH-F.in.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	2006/02/21 14:03			